

TRACK INSPECTION REPORTING FORM

Date 2/17/14

Page 1 of 1

(Please Print)

Grave Seal 1

1393208

4 V

cut resistance

[illegible]

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED

Riding Inspection ☒ SNOW Covered

100

Were Switch in the area of Inspected Yes _____ NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes NO

Reason for special inspection ?

Track Inspector Signature

Michael Rabb

Supervisory Certification

on 

TRACK INSPECTION REPORTING FORM

Name Michael L. Ballard Date 2-18-2014 Page 1 of 1
 (Please Print)
 Watchman Lutherville To Cold Spring
 W.O Number 1394928

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	<u>Kidding inspection snow covered tracks</u>
	<u>NO new defects noted</u>
	<u>Track inspection complete</u>

COPY

COPY

Were Switch in the area of Inspected Yes _____ NO _____
 Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
 Yes _____ NO _____

SPECIAL INSPECTION Yes _____ NO _____

Reason for special inspection ? _____

Track Inspector Signature

Supervisory Certification

Michael L. Ballard

[Signature]

TRACK INSPECTION REPORTING FORM

Name Mike Atkins / Steve Sell Date 2/18/14 Page 1 of 1
(Please Print)

Watchman _____ W.O Number 1395011
Inspected From Cold Spring To Camden / Penn

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	RISING INSPECTION SNOW COVERED -
	NO NEW DEFECTS

COPY

Were Switch in the area of Inspected Yes _____ NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
Yes _____ NO ☒

SPECIAL INSPECTION Yes _____ NO ☒

Reason for special inspection ? _____

Track Inspector Signature

Michael A. Atkins

Supervisory Certification

[Signature]

TRACK INSPECTION REPORTING FORM

Name Rolland Date 2-19-2014 Page 1 of 1
 (Please Print)

Watchman _____ W.O Number 1394343
 Inspected From Campbell yards To Lithium

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

No Track inspection attended Driver improvement program class

COPY

Were Switch in the area of inspected Yes _____ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?
 Yes _____ NO

SPECIAL INSPECTION Yes _____ NO

Reason for special inspection ? _____

Track Inspector Signature

Michael L. Rolland

Supervisory Certification

[Signature]

TRACK INSPECTION REPORTING FORM

Name M. Alchin Date 2/19/14 Page 1 of 1
 (Please Print)
 Watchman _____ W.O Number 1394346
 Inspected From CINTH To CROM / BWI

	Exception Chain Marker No.		W.O.	Track	Rail	Switch	Codes		Status	Repair
Item	From	To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

M. ALCHIN / S. SELL / G LAM
ATTENDED DRIVER IMPROVEMENT PROGRAM
DID NOT PERFORM INSPECTION DUE TO
LENGTH OF TRAINING CLASS.

Were Switch in the area of Inspected Yes _____ NO ☒

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ☒

SPECIAL INSPECTION Yes _____ NO _____

Reason for special inspection ? _____

Track Inspector Signature

Michael Alchin

Supervisory Certification

[Signature]

COPY

TRACK INSPECTION REPORTING FORM

Name Bollard Schister Date 2-20-2014 Page 1 of 1

(Please Print)

Watchman

In ted From

To

W.O Number:[illegible]

Item	COMMENTS
------	----------

No new defects noted.

Track inspection complete



Were Switch in the area of Inspected Yes _____ NO _____

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?

Yes _____ NO

SPECIAL INSPECTION Yes____. NO____

Reason for special inspection ?

Track Inspector Signature

Supervisory Certification

on 1/2/2017

TRACK INSPECTION REPORTING FORM

Name Mike Alchin / Steve Sell Date 2/20/14 Page 1 of 1
(Please Print)

Watchman _____
 Inc. Registered From LUTH To CS.

[illegible]

Item	COMMENTS
------	----------

Snow Covered / Riding Inspection
NO NEW DEFECTS NOTED.

Were Switch in the area of Inspected Yes _____ NO 1

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO ✓

SPECIAL INSPECTION Yes____. NO X

Reason for special inspection ? _____

Track Inspector Signature

Supervisory Certification

TRACK INSPECTION REPORTING FORM

Name Pollard, Bryant Date 2-22-2014 Page 2 of 2
 Watchman (Please Print) T. Schuster W.O Number 1393133
 Inspected From Linthicum To Croftwell

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.				2		488-1	5312	348	Y	A
2.	48240			1			m310	318	Y	A
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	Switch area needs to be dressed this would put down on files caused by switch heaters, 1 rotted tie 9"
2	derail sign missing
	Track inspection complete

Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
 Yes NO

SPECIAL INSPECTION Yes NO

Reason for special inspection ?

Track Inspector Signature

B. Michael Pollard

Supervisory Certification

[Signature]

TRACK INSPECTION REPORTING FORM

Name GLAM Ssell Date 2/24/2014 Page 1 of 1
 (Please Print)
 Watchman M ALCHIN W.O Number 1400743
 Inspected From HV To Lutherville

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

NO NEW DEFECTS NOTED IN AREA

TRACK INSPECTION ALSO CONSISTED

OF LARRY WHITE MDOT

BILL MATHEWS TRANSPORTATION RESOURCE ASSOCIATES, INC

JOSHUA SHIK " " " "

JULIE B. THOMPSON " " " "

OBSERVING THE RWP PROGRAM IN PLACE.

Were Switch in the area of Inspected Yes ☒ NO ☐

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes ☒ NO ☐

SPECIAL INSPECTION Yes ☐ NO ☒

 **COPY**

Reason for special inspection ? _____

Track Inspector Signature B Lamy

Supervisory Certification [Signature]

TRACK INSPECTION REPORTING FORM

Name Pollard Date 2-26-2014 Page 1 of 2
 (Please Print)
 Station Litchfield To Cromwell W.O Number 140 1805
 Inspected From

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.										
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item	COMMENTS
	Riding inspection due to snow
	Track inspection complete


 **COPY**

Were Switch in the area of Inspected Yes _____ NO _____
 Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
 Yes _____ NO _____

SPECIAL INSPECTION Yes _____ NO _____

Reason for special inspection ? _____


Track Inspector Signature


Supervisory Certification


Name Pollard Date 2-26-2014 Page 1 of 1
(Please Print)
Station W.O Number 1401802
Inspected From Camden yards To Lithicum

[illegible]

Item	Comments
	Riding inspection due to inclement weather Track inspection complete

 COPY

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO _____


SPECIAL INSPECTION Yes____. NO____

Reason for special inspection ? _____

Track Inspector Signature

Supervisory Certification


Track Inspector Signature *Michael Ballard*

Supervisory Certification 

Name Pollard Date 2-27-2014 Page 1 of 1
(Please Print)
Stationman Bryant W.O Number 14007.33
Inspected From Hunt Valley To Lutherville

[illegible]

Item	Comments
1	Styro Foam in track area, needs to be cleaned up
	Track inspection complete.



Were Switch in the area of Inspected Yes NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?
Yes NO

SPECIAL INSPECTION Yes____. NO____/

Reason for special inspection ? _____

Track Inspector Signature

Supervisory Certification

Supervisory Certification 

TRACK INSPECTION REPORTING FORM

Page of

W.O Number 1400740

↗ S

[illegible]

Item	COMMENTS
------	----------

NO NEW DEFECTS NOTED IN AREA

Were Switch in the area of Inspected Yes ✓ NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO 1

SPECIAL INSPECTION Yes____. NO ☒

Reason for special inspection ?

Track Inspector Signature

Supervisory Certification

TRACK INSPECTION REPORTING FORM

Name T SCHISLER M POWARD

Date 2/28/2014

Page 1 of 3

(Please Print)

.. atohman W BRYANT

W.O Number 1400605

Inspired From Coco Springs

To CRUDEN

[illegible]

Item	COMMENTS
------	----------

1 10' TO 15' FENCE LOOSE, TOP BAR BROKEN OFF, 1 FENCE POST BENT.

Were Switch in the area of Inspected Yes X NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position ?

Yes _____ NO X

SPECIAL INSPECTION Yes____. NO X

Reason for special inspection ? _____

Track Inspector Signature

T School

Supervisory Certification _____